

PUBLIC WORKS DEPARTME<u>NT (</u>B & B), HARYANA Office of Executive Engineer, Provincial Division, PWD B&R Br., Faridabad. Tele = 0129-2288157 Email II): pwd-cepdl-f<u>aridabad@fary</u>,ni<u>n.in</u>



Memo No. 9419

The Principal,

St. Columbus School,

Dayal Bagh, Surajkund Faridabad.

Subject:-

NOC for building structure safety certificate for St. Columbus School, Dayal Bagh, Surajkund, Faridabad.

Reference;-

Your office letter no. SCS/25/05/5761 dated 23/05/2025.

In the connection of above cited subject, it is submitted that the above said school building is inspected by the Sub Divisional Engineer, Provincial Sub Division No.3, PWD B&R Br., Faridabad alongwith concerned, Junior Engineer of this office on 17/06/2025 and found that the School building having basement (There are I no. computer lab, I shooting hall, I no. humanities lab, common area, I no, staircase are exist at the basement floor level), Ground floor, First Floor, Second Floor & Third Floor.

The building is having frame structure with column beams and R.C.C. slab, ramp & load bearing walls. The structure stability certificate has been also enclosed, which issued by Shiv Kumar Gupta, Chartered, Structure Engineers & Government Approved Valuer, office: LG-2, Vishnu Palace, Neelam Flyover, Sector-20B, Faridabad on dated 30/05/2022. The fire NOC has been issued by the Assistant Divisional Fire Officer/ Fire Station, Sector-15A, Faridabad memo no. FS/2023/284 dated 05/4/2023 valid upto 04/04/2026 . The Hygiene certificate is also issued by O/o Deputy Civil Surgeon, Faridabad vide their office No. 2/SDV/25-26 dated 11/04/2025.

Keeping in view all the circumstance the building of St. Columbus School, Dayal Bagh, Surajkund, Faridabad is seems to be safe and this office has no objection to give safety certificate with validity of one year. Periodical inspection must be insured.

DA/-Nil

Executive Engineer, Provincial Division, PWD B&R Br Earidabad

Endst. No.

Dated

Copy forwarded to the Sub Divisional Engineer, Provincial Sub Division No.3, PWD B&R Br. Faridabad for information and necessary action w.r.t. his office letter memo no. 1897 dated 01/07/2025.

DA/ Nil

Executive Engineer, Provincial Division. PWD B&R Br. Faridabad

BUILDING SAFETY CERTIFICATE

No

Dated: 4/7/9#25

It is certified that the existing building St. Columbus School at Dayal Bagh, Surajkund, Faridabad is having block(s)/Floor(s) as per details below.

Details of Block(s) in School	Block (1)	-1	Block (2)		Block (3)	 Block (4) Nii	
No. of Floor(s) in	Basement to		Nil	1	Nil	INII	
the Block	Third floor	- 11-		L -		 	- 1

The building is owned/occupied by St. Columbus School have complied with the Building safety requirements in accordance with National Building Code Rules and verified by the officers concerned of PWD B&R Br. Faridabad on 17.06.2025 in the Presence of Shri Rishi Chaudhary (President) and that the building/premises is fit for occupancy for running school with effect from .51.112-75.... for a period of One year i.e. upto 31.03.2026 in accordance with rule and subject to compliance of the specific conditions as appended.

- Periodical inspection of school building must be ensured.
- Time to time maintenance of school building must be ensured.

Issued on ... 41712975, at PWD B&R Br. Faridabad by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name

Designation:

Indraj Singh

Sub Divisional Engineer Provincial Sub Division No.3

PWD B&R Br. Faridabad

PWD B&R Br. Faridabad

Sector-16A, Faridabad

Name & Address of Department/Office :